



NOTE:
STANDOFF BRACKET LOCATIONS
ARE ± 1".
DO NOT PREDRILL HOLES IN THE
STRUCTURE.
HOLES SHOULD BE MATCH DRILLED
TO INSURE PROPER ALIGNMENT



3D MODEL AVAILABLE IN STEP FILE FORMAT ON OUR WEBSITE

| | | | | |
|---|------------|---|--|----------|
| DRAWN SB | 12/28/2016 | <div>Cotterman®</div> <div>Division of Material Control, Inc. 130 Seltzer Road, Croswell, Michigan 48422 U.S.A.</div> | | |
| CHECKED | | | | |
| APPROVED | | TITLE | | |
| PART 3570355 F39S FOR CATALOG | | F39S | | |
| THIS PRINT IS PROPERTY OF COTTERMAN® COMPANY, AND MAY NOT BE USED IN WHOLE OR PART WITHOUT WRITTEN PERMISSION. | | Drawing is computer generated, and print might not be to scale | | |
| | | SIZE C | DWG NO 3570355 F39S FOR CATALOG.dwg | REV A |
| | | DIMENSIONS IN INCHES UNLESS NOTED | | |
| | | SHEET 1 OF 1 | | |